



Mottagare: Kontrollanter, kontrollantelever, CI alla klubbar	Datum: 2019-10-09	BilagService Bulletin	Blad nr: 1 av 1
Fastställt av MK: 2019-10-09		Ersätter:	
Utlärdare: SFF Materielkommitté (MK)		Ärende: Materielvarning nr. 2019/3	

Bakgrund

För att undvika en möjlig fördröjning av reservutlösningen skall monteringen av RSL linan ändras.

Omfattning

System Wings: RSL med ”Reserve Boost M.A.R.D.”

Åtgärd

Ändrad montering enligt Service Bulletin.

När

Före nästa ompackning.

Vem

Kontrollant 2 eller 3

Bilaga

Sunrise Manufacturing, Service Bulletin #: 081018

Sunrise Manufacturing International, Inc.

4035 Correia Dr. • Zephyrhills, Florida 33542 • Phone 813-780-7369 • Fax 813-788-2799

www.skydivewings.com



Date: 10 October 2018	Service Bulletin #: 081018	# of pages: 6
Subject: RSL with Reserve Boost Mard (Main Assist Reserve Deployment)		
Status: Mandatory		

Identification:

- RSL with Reserve Boost Mard (Main Assist Reserve Deployment)

Background:

A jumper with the Wings Reserve Boost System had a Reserve Deployment Hesitation involving the Lanyard and Reserve Ripcord Cable. After evaluation of the incident we have decided to modify the Reserve Boost Assembly. This modification is **Mandatory** on or before your next reserve repack. Please see the pictures with text and follow these instructions to modify your Reserve Boost to the new configuration.

Service Bulletin:

This Service Bulletin involves Reserve Ripcord Cable/Pin and Reserve Boost Lanyard.

Authority:

Henri Pohjolainen, President
Sunrise Manufacturing Inc.
4035 Correia Dr.
Zephyrhills, FL
33542
(813) 780-7369


Distribution:

All registered owners affected by the service bulletin
All Sunrise Manufacturing, Inc. Dealers
Parachuting Publications
FAA MIDO Orlando, FL
FAA ACO Atlanta, GA
PIA Technical Committee

Follow these Instructions for changing the RSL Lanyard for the “*Reserve Boost*” M.A.R.D. device on *Wings* Harness/Containers.




Original RSL for “Reserve Boost” on ***Wings*** Reserve Containers.



Notice “Lark’s Head” knot on the ring.



Remove HMA line from the mini ring.



Pass the mini ring through the opening between the ring and the Zig-zag stitching on the T-IV RSL.



Pass the mini ring of the HMA line through the loop on the end of the "Reserve Boost" lanyard.



Tighten the knot formed.

Follow these Instructions for Installing the RSL Lanyard for the “Reserve Boost” M.A.R.D. device on Wings Harness/ Containers.



Pass the Ripcord cable through the mini ring of the RSL.



Pass the Ripcord cable through the mini ring on the **Wings** container.



Pass the Ripcord cable and the Top Reserve Closing Flap under the T-IV retaining webbing.

The Reserve Container is ready to be closed.

Follow the Instructions in the **Wings** Owner's Manual to close the Reserve Container.